

























<b>WTG Inspection Observations</b>					
	Good			Date	
	Minor			WTG	
	Medium			Site	
	Critical			State	


Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
1	Capacitor panel condition and connection OK	Good				Bottom Panel
2	Control panel and Power panel condition Good	Good				Bottom Panel
3	Control panel and Power panel condition Good	Good				Bottom Panel
4	Nacelle control panel door damage, Not able to close, Filter damage	Critical			Door hinges need to change and close door	Nacelle panel








<b>WTG Inspection Observations</b>					
	Good			Date	
	Minor			WTG	
	Medium			Site	
	Critical			State	

Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
5	Nacelle control panel fully dusty	Medium			Need to clean and fix door	Nacelle panel
6	Wind speed and wind direction sensor in good condition	Good				Nacelle panel
7	Nacelle is fully dirty with grease and oil, Unsafe condition	Critical			Complete Nacelle need to clean	Nacelle
8	Nacelle is fully dirty with grease and oil, Unsafe condition	Critical			Complete Nacelle need to clean	Nacelle


<b>WTG Inspection Observations</b>					
	Good			Date	
	Minor			WTG	
	Medium			Site	
	Critical			State	







Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
9	Rotor lock breaking Electrical system not working	Critical			Need to repair or replace system	Nacelle
10	Nacelle main carrier fully rust	Critical			Main carrier fully rusted, need to remove rust and repainting require	Nacelle
11	Nacelle main carrier fully rust	Critical			Main carrier fully rusted, need to remove rust and repainting require	Nacelle
12	Hub body part fully rusting and its connection hardware found rusting	Critical			need to remove rust and repainting require	Hub


<b>WTG Inspection Observations</b>					
	Good			Date	
	Minor			WTG	
	Medium			Site	
	Critical			State	




Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
13	Hub body part fully rusting and its connection hardware found rusting	Critical			need to remove rust and repainting require	Hub
14	Pitch motor and Drive in good condition	Good				Hub
15	Pitch sensor and Lubrication system in good condition	Good				Hub
16	Pitch control panel in good condition	Good				Hub



<b>WTG Inspection Observations</b>					
	Good			Date	
	Minor			WTG	
	Medium			Site	
	Critical			State	

Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
17	Hub inside fully grease spillage, Unsafe condition	Critical			Hub in side grease need to clean	Hub
18	Blade condition found OK with visual inspection	Good				Blade
19	Blade condition found OK with visual inspection	Good				Blade
20	Safety rail OK	Good				Blade

<b>WTG Inspection Observations</b>					
	<b>Good</b>			<b>Date</b>	
	<b>Minor</b>			<b>WTG</b>	
	<b>Medium</b>			<b>Site</b>	
	<b>Critical</b>			<b>State</b>	

Sr.	Observations / Remarks	Category	Photographs 1	Photographs 2	Remarks	WTG Area
21	Blade scurt damage	Minor			need minor repairing	Blade
22	One Blade found paint removed, Suspect blade repairing	Critical			Need Historical data of blade	Blade

